

FIELD INSPECTION REPORT

MMBisy (SC)

Date of Inspection :	16-12-2020	District:	West Champaran
Division :	Nankatiyaganj	Length (km):	0.725 km
Name of the Road:	Kukana ward NO-01 to ward NO-02		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		Completed
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S	
b)	Condition of Surfacing	S	
c)	Riding Quality	S	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S	
f)	Contraction Joints provided or not (CC Pavement)	-	
g)	Compaction of flank/slope & raincuts if any	S	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	-	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-	
c)	Condition of railings/slab/approach for Bridges	-	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S	
4.	Compliance History		
a)	Status of ATR's & any others	-	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

B. Kumar
16/12/2020
(Signature)

NAME: BIPIN KUMAR

DESIGNATION: J.E.