

FIELD INSPECTION REPORT

Date of Inspection : 07.01.2021	District: DARBHANGA
Division : BENIPUR	Length (km):
Name of the Road: KATHWAR WEST TO LAKSHMI GINGH ROUSE TO KAMLA BORDA WEST	
Scheme/Programme: MAINTENANCE	NABARD
Package No.:	Road Id No.:
Status of the Project: ☒ Ongoing/Completed/Under Maintenance	
Work is a case of: ☒ New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	☒ S/U
b)	Condition of Surfacing	☒ S/U
c)	Riding Quality	☒ S/U
d)	Road Camber	☒ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	☒ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	☒ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	☒ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	☒ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	☒ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Pradeep Kumar
17/01/2021
J-E

Chaiti
7/1/2021
AE

(Signature)

NAME: PRADEEP KUMAR

DESIGNATION: J-E