## FIELD INSPECTION REPORT

Date of Inspection :			District:		
Division :			Length (km):		
Name of	the Road:	14149 \$ 70	Po Horiso do la		
Scheme/	Programme:	MAINTENANCE	730000 72.70		
Package	No.;		Road Id No.:		
Status of the Project: Ongoing Work is a case of: New Con		Ongoing/Complete	Completed/Under Maintenance		
T-0	a case of:	New Connectivity/	Up gradation/ Maintenance		
\$1. No.	2000年	Parameters to	be checked	Remarks	
de t	Pavement	<b>。在19</b> 00年	是1000年间,2000年,1000年,1000年	AND THE PERSON NAMED IN	
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			s/u	
c)	Riding Quality •			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Drains	ge Emilie	1808年为公司。	N = 12 12 12 1	
a)	Condition of head walls in Hume pipe culverts including its painting				
	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U S/SRI/U	
	Condition of railings/slab/approach for Bridges			S/SRI/U	
31	Road Eurnite	re		44.00 S	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4	Compliance l	listory20	國家提供的		
8)	Status of ATR	's & any others	50	- Tarab	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	
and adulate	MA

work not stated.

(Signature)

NAME:

DESIGNATION: