FIELD INSPECTION REPORT

Date of	Inspection: 31.12.2020 District: Burner	
Divisio	n: Rrw. n	
Name o	of the Road: Budband Length (km): 1.23 KM	1
Schem	of the Road: Budhaila PMGsy Shiv Gobal for No.: Road Id No.:	andey ke go
Packag	Road Id No.:	Tetalatgo
Status	of the Project: Ongoing Completed Under Maintenance	
Work	s a case of: New Connectivity/Up gradation/ Maintenance	
SI. No.		Remarks
1.	Pavement	-1
a)	Road Junction condition	<i>y</i> eu
b)	Condition of Surfacing	\s/U
c)	Riding Quality	√8/U
d)	Road Camber	√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	A STATE OF THE PARTY OF THE PAR
n	Contraction Joints provided or not (CC Pavement)	Yes/No 1
g)	Compaction of flank/slope & raincuts if any	Nes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NY
3.	Road Furniture	
a)	Whether sign boards/informatory/eautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

3/12/2010

(Signature)

