

FIELD INSPECTION REPORT

Date of Inspection : 08 01 2021		District: DARBHANGA
Division : BENIPUR		Length (km):
Name of the Road: - L026 TO RAJAKHARWAR DAKSHIN TOLA.		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project: ☒ Ongoing/ ☐ Completed/ ☐ Under Maintenance		
Work is a case of: ☒ New Connectivity/ ☐ Up gradation/ ☐ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	☒ S/ ☐ U
b)	Condition of Surfacing	☒ S/ ☐ U
c)	Riding Quality	☒ S/ ☐ U
d)	Road Camber	☒ S/ ☐ U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ☒
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	☒ S/ ☐ SRI/ ☐ U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	☒ S/ ☐ SRI/ ☐ U
c)	Condition of railings/slab/approach for Bridges	☒ S/ ☐ SRI/ ☐ U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	☒ Yes/ ☐ No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	(5)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

08/01/2021
J.E

Shashi
8/1/2021
A.E

(Signature)

NAME: PRADEEP KUMAR

DESIGNATION: - J.E