## FIELD INSPECTION REPORT

Date of Ir	nspection: 2-1 12 20 District:	
Division	Coboo to con Catellack Length (km): 013.70 Cor	
	the Road: Palma masaurhi Road to sampat	dak gram mallah North side
	LAMAINTENANCE 1	
Package	Road Id No.:	
	- In Compicted Under Manne	
	Connectivity/Up gradation/ Maintenance	· Company and
\$1. No.	· · · · · · · · · · · · · · · · · · ·	Remarks
		\$
a)	Road Junction condition	\$
b)	Condition of Surfacing	
	Riding Quality	\$
c)		S
d)	Road Camber  Whether free from defects such as visible cracks, exposed	S
e)	Whether free from detects such as recording aggregates in case of CC Pavement.	
	Contraction Joints provided or not (CC Pavement)	S
f)	Contraction Joints provided of No. (50	5
g)	Compaction of flank/slope & raincuts if any	11. 5 松中國
2	Cross Drainage	110
ALL PARTY OF THE P	Condition of head walls in Hume pipe culverts including its painting	1.7.
a)	Condition of Abutment & Wing walls, Slab in RCC culverts	NIA
b)	Condition of Abutment & Wing Water, Sind Land	11/A
c)	Condition of railings/slab/approach for Bridges	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
133	Road Furniture	With All Said
8)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	1890
<b>建</b> 和	Compliance History	
a)	Status of ATR's & any others	
,	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	

Overall Rating

- 44 <u>.01</u>	0.
Satisfactory (S)	3,
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	235 253

(Signature)

NAME:

Supriya Rani TON: AE Sampatchale.

DESIGNATION:

: