

These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work:- Repair of road breaches (damaged by flood) in Barba Khurd to Mangalpur Semara.					
Workhead:- F.D.R.					
Item no. 1 Elve constn of					

embankment with approved material obtained from borrow pit — 8 IT.

2nd km.

$$100'5 \times 21 \times \left(1 + \frac{1.16}{2} \times 0.80 + 1\right) = 19.85 \text{ m}^3$$

$$100'5 \times 9 \times \left(1 + \frac{1.26}{2} \times 0.60 + 1\right) = 7.92 \text{ m}^3$$

$$100'5 \times 20 \times \left(0.9 + \frac{1.1}{2} \times 0.70 + 1\right) = 15 \text{ m}^3$$

$$100'5 \times 15 \times \left(0.80 + \frac{1.26}{2} \times 1 + \frac{1.24}{2}\right) = 16.80 \text{ m}^3$$

$$100'5 \times 52 \times \left(0.80 + \frac{1.0}{2} \times 1 + \frac{1.26}{2}\right) = 51.48 \text{ m}^3$$

$$100'5 \times 13 \times \left(0.80 + \frac{0.96}{2} \times 0.70 + 1\right) = 8.84 \text{ m}^3$$

3rd km.

$$100'5 \times 58 \times \left(0.8 + \frac{1.6}{2} \times 0.9 + 1\right) = 49.59 \text{ m}^3$$

check
P. E.

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of item					
item no. 2 E/W - constn of embankt obtained from borrow pit - E/L					
Qty Vol T.M.B. per (2)					
453.27 m ³ @ Rs 130.5/m ³					59151.7
item no. 2 providing and la					
bours for dry					
graded break					
bat including					
light ramming etc					

Qty Vol T.M.B. per (3)

226.85 m³ @ Rs 1782.76/m³ Rs 404419.11

item no. 3 providing filling
sand bag, stitching
and placing etc

E/L

Qty Vol T.M.B. per (3)

128 no's @ Rs 24.59/each Rs 3147.52

Rs 466718.36

Add S.F. ————— Rs 47221.51

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Add 1x1.6C					Rs 4667.00
Add 12x. GST					Rs 456006.60
					Total Rs 574612.00
M/sn 3/08/2020 Jr 24/12/2020 C/P R. D. S. 24/12/2020					