FIELD INSPECTION REPORT

Date of Inspection: 커네아			District:	Katih	ar		
Name of Road:		Mangrown	pwo	Road	To Hara	Tola.	
Scheme/	Programme:	MAINTENAI	NCE				-
Package	No.		Road ID No.		-	,	1
Status of	the Project:	Onging/Cor	npleted/Unde	r Mainte	nance		:
Work is a	case of:	New Connectivity/ Up Gradation/ Maintenance					
SI.No	Parameters to be Checked					Remarks	
1	Pavement				1-2-2-		- 154
a)	Road Junction Condition					,87U	
b)	Condition of Surfacing					S/U	
c)	Riding Quality						S/U/
d)	Road Camber						S/U/
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement						of Yes/No
f)	Contraction Joints provided or not (CC Pavement)					¥es/No	
g)	Compaction of flank/slpoe & raincuts if any					Yes/No	
2	Cross Drainage						
a)	Condition of headwalls inn Humepipe culverts including its painting					<i>J\$1</i> \$B1/U	
b)	Condition of Abutment & Wings walls, Slab in RCC culverts					√8/SRI/U	
c)	Condition of railings/slabs//approach for Bridges					_S/∕SRI/U	
3	Road Furniture						
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.					Yes/No	
4	Compliance History	У					
a)	Status of ATR & an	y others					

Overall Grading:

Satisfactory (S)	
Satisfactory but requires Improvement(SRI)	SED
Unsatisfactory (U)	

Name: Amrendra Nath Trakur Degisnation Junior Byinean