

FIELD INSPECTION REPORT

Date of Inspection: 07/01/2021		District: Katihar
Name of Road:		RBO Prampur hata Road To Balua Tola.
Scheme/ Programme:	MAINTENANCE ✓	
Package No.	Road ID No.	
Status of the Project:	Ongoing/Completed/Under Maintenance ✓	
Work is a case of:	New Connectivity/ Up Gradation/ Maintenance ✓	
Sl.No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2	Cross Drainage	
a)	Condition of headwalls in Humepipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wings walls, Slab in RCC culverts	S/SRI/U ✓
c)	Condition of railings/slabs/approach for Bridges	S/SRI/U ✓
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/Pavement road markings are provided and maintained.	Yes/No ✓
4	Compliance History	
a)	Status of ATR & any others	

Overall Grading:

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Name:
Designation

Amrendra Nath Thakur.
JE

07/01/2021
(Signature)