FIELD INSPECTION REPORT

Date of Inspection: Hollon District: Kathan					
Name of		5010 (F	District: Kathan reposed Ruad) To poshia Tolo	A	
Scheme/ Programme:		MAINTENANCE			
Package No. Road II			Road ID No.		
Status of	tatus of the Project:		Onging/Completed/Under Maintenance		
Work is a	case of: New Connectivity/ Up Gradation/ Maintenance				
Sl.No	Bondon of Graduation, Maintenance				
1	Pavement	Paral	meters to be Checked	Remarks	
a)	Road Junction Condition				
b)	Condition of Surfacing				
	Riding Quality			S	
	Road Camber			S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			S	
f)	Contraction Joints provided or not (CC Pavement)			V	
	Compaction of flank/slpoe & raincuts if any			V	
THE RESERVE TO SERVE THE PARTY OF THE PARTY	Cross Drainage				
a)	Condition of headwalls inn Humepipe culverts including its painting				
	Condition of Abutment & Wings walls, Slab in RCC culverts			S	
c)	Condition of railings/slabs//approach for Bridges			3	
3	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.				
4	Compliance History		The second of th		
a)	Status of ATR & any others				
Satisfactor		Satisfactory Satisfactory Unsatisfactor	but requires Improvement(SRI)	S	
				Lean	

Name: Amrendro Noth Thaleur Degisnation J.B (Signature)