FIELD INSPECTION REPORT

Date of Ir	nspection: o#oil	District: Katihorn Road To Bathana Chitouriya santali Tola.					
Name of	•	bHazz	Road	ToBa	thang	chitouniya.	santali Tola.
Scheme/ Programme:		MAINTENANCE					
Package	No.		Road ID	No.			
	the Project:	Onging/Con	mpleted/Under Maintenance				
Work is a		New Connectivity/ Up Gradation/ Maintenance					
SI.No.		Parar	neters to	be Che	cked		Remarks
1	Pavement	TATAS:				The state of the s	A CONTRACTOR OF THE PERSON OF
a)	Road Junction Condition						٤
b)	Condition of Surfacing						S
	Riding Quality						S
d)	Road Camber						5
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement						À
f)	Contraction Joints provided or not (CC Pavement)						4
g)	Compaction of flank/slpoe & raincuts if any						
2	Cross Drainage						
a)	Condition of headwalls inn Humepipe culverts including its painting						SRL
b)	Condition of Abutment & Wings walls, Slab in RCC culverts						SRC
c)	Condition of railings/slabs//approach for Bridges						SPL
A STATE OF THE PARTY OF THE PAR	Road Furniture						
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.						γ-
4	Compliance History						
a)	Status of ATR & any others						
Overall G	rading:	Satisfactory (S) Satisfactory but requires Improvement(SRI) Unsatisfactory (U)					SRL
							Contact to the second

Name: Amrendro Noth Hakun Degisnation J.B

(Signature)