

FIELD INSPECTION REPORT		
Date of Inspection :- 14-12-2020		District- Vaishali
Division :- Hajipur		Length (K.M) - 1.035
Name of the Road : Lodgari Jatkauli Road to Abulhasanpur Bhumihasa tola		
Scheme /Programme : M.M.C.S.Y		
Package no :-		Road Id No. :
Status of the Project : - Ongoing/ Completed/ Under Maintenance		
Work is a case of : New Connectivity/ Up gradation/ Maintenance		
Sl. NO.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction Condition	✓ S/U
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/ No
f)	Contraction Joints provided or not (CC Pavement)	Yes/ No
g)	Contraction of flank/Slope & raincuts if any	Yes/ No
2	Cross Drainage	
a)	Condition of head walls in Hume Pipe culverts including its painting	S/ SRI/U
b)	Condition of Abutment & Wing Walls, Slab in RCC Culverts	S/ SRI/U
c)	Condition of Railings/slab/approach for Bridges	S/ SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	✓ Yes/ No
4	Compliance History	
a)	Status of ATR/s & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but Requires Improvement (SRI)	SRI U
Unsatisfactory (U)	

Name :

Designation :

[Signature]
14/12/20
J.E. Vaishali
Signature