FIELD INSPECTION REPORT

			EL RIVITAGE I ORI		
Distance of the State of	of Inspection:	71112021	District:	istali	
Divis	· [a	liner	Length (km): 0.2	2014	
	e of the Road: P	c.c. Bylass roo	ol to Mahadalit Tala	Vie Prince	La Company
	ne/Programme:	MAINTENANCE		- Hujery	and the same
A-marine management	of the Project:	Ongoing/Complet	Road Id No.:		
Work is a case of:		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance			
SI. No			to be checked	nance	a Thirteen Commission of the C
5 5 0 4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		ranameters	to be checked		Remarks
1.	Pavement			and an incompact according to the state	
a)	Road Junction condition				S/U
b)	Condition of Surfacing				S/U
c)	Riding Quality				S/U
d)	Road Camber S				S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				Yes/No
f)	Contraction Joints provided or not (CC Pavement)				Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainag	e			
a)	Condition of head walls in Hume pipe culverts including its painting			1	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				S/SRI/U
2)	Condition of railings/slab/approach for Bridges			S/SRI/U	
	Road Furnitur				
			ry/cautionary Board are provided and mai		m Yes/No
C	ompliance Hi	tory			
S	tatus of ATR's	& any others		Venza	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) Y

NAME: NAND UISHOR SHARMA

DESIGNATION: junior Engineet