

# FIELD INSPECTION REPORT

|                                                    |                                            |
|----------------------------------------------------|--------------------------------------------|
| Date of Inspection : 11-01-2021                    | District: katihar                          |
| Division : Barsoi                                  | Length (km): 0.530                         |
| Name of the Road: Sagdar to Kachera Mahadalit tola |                                            |
| Scheme/Programme: MAINTENANCE                      | MMCBS                                      |
| Package No.:                                       | Road Id No.:                               |
| Status of the Project: Ongoing/Completed           | Under Maintenance                          |
| Work is a case of:                                 | New Connectivity/Up gradation/ Maintenance |

| Sl. No. | Parameters to be checked                                                                                             | Remarks     |
|---------|----------------------------------------------------------------------------------------------------------------------|-------------|
| 1.      | Pavement                                                                                                             |             |
| a)      | Road Junction condition                                                                                              | S/U         |
| b)      | Condition of Surfacing                                                                                               | S/U         |
| c)      | Riding Quality                                                                                                       | S/U         |
| d)      | Road Camber                                                                                                          | S/U         |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | N/A Yes/No  |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | N/A Yes/No  |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No      |
| 2.      | Cross Drainage                                                                                                       |             |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U     |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | N/A S/SRI/U |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | N/A S/SRI/U |
| 3.      | Road Furniture                                                                                                       |             |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No      |
| 4.      | Compliance History                                                                                                   |             |
| a)      | Status of ATR's & any others                                                                                         | No          |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | — |
| Satisfactory but requires Improvement (SRI) | S |
| Unsatisfactory (U)                          | — |

Mh  
09/01/2020  
(Signature)

NAME: Mr. h. s. kumar  
DESIGNATION: J.E