

FIELD INSPECTION REPORT

Date of Inspection :	08-01-2021	District:	Nalanda
Division :	Hills 2	Length (km):	0.600 km
Name of the Road:	Amar Gvaspur Mubhya Mantri road to Shaktinagar		
Scheme/Programme:	MAINTENANCE	M.M.G.S.Y.	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance - Under Maintenance		
Work is a case of:	New Construction/Up gradation/Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U - S
b)	Condition of Surfacing	S/U - S
c)	Riding Quality	S/U - S
d)	Road Camber	S/U - S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No - Yes
f)	Construction Joints provided or not (CC Pavement)	Yes/No - Yes
g)	Correction of Bank/slope & rainwater if any	Yes/No - Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U - S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U - N/A
c)	Condition of railings/slab/approach for Bridges	S/SR/U - N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No - Yes
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SR1)	
Unsatisfactory (U)	

H
08/01/2021
AE
(Signature)