

FIELD INSPECTION REPORT

Date of Inspection: 21.12.2020		District: East Champaran
Division: Chakea		Length (Km): 0.600 Km
Name of the Road: Praduman Chhapra to Muslim Jola		
Scheme/Programme:		MAINTENANCE GTSNY
Package No.:		Road ID No.:
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up Gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1,	Pavement	S
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes
g)	Compaction of flank/slope & raincuts if any	SRI
2,	Cross Drainage	SRI
a)	Condition of head walls in Hume pipe culverts including its painting	Damage
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	Damage
c)	Condition of railings/slab/approach for Bridges	Damage
3,	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	Not available
4,	Compliance History	
a)	Status of ATR's & any others	SRI

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	SRI
	Unsatisfactory (U)	

Note → Due to flood 2020, Damaged badly.

(Signature) 21.12.2020

NAME: Arun Kumar Chakraborty

DESIGNATION: J.E