

# FIELD INSPECTION REPORT

|                                                      |                                            |
|------------------------------------------------------|--------------------------------------------|
| Date of inspection : 09-01-2021                      | District: Kotihar                          |
| Division : Barsoi                                    | Length (km): 0.420                         |
| Name of the Road: Madarso to B Sikarna to PMGSY Road |                                            |
| Scheme/Programme: MAINTENANCE                        | GT/MSY                                     |
| Package No.:                                         | Road Id No.:                               |
| Status of the Project:                               | Ongoing/Completed/Under Maintenance        |
| Work is a case of:                                   | New Connectivity Up gradation/ Maintenance |

| Sl. No. | Parameters to be checked                                                                                             | Remarks     |
|---------|----------------------------------------------------------------------------------------------------------------------|-------------|
| 1.      | Pavement                                                                                                             |             |
| a)      | Road Junction condition                                                                                              | ✓S/U        |
| b)      | Condition of Surfacing                                                                                               | ✓S/U        |
| c)      | Riding Quality                                                                                                       | ✓S/U        |
| d)      | Road Camber                                                                                                          | ✓S/U        |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | ✓Yes/No     |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | ✓Yes/No     |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No ✓    |
| 2.      | Cross Drainage                                                                                                       |             |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SR/U      |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | N/A S/SRI/U |
| c)      | Condition of railings/slab approach for Bridges                                                                      | N/A S/SRI/U |
| 3.      | Road Furniture                                                                                                       |             |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No      |
| 4.      | Compliance History                                                                                                   |             |
| a)      | Status of ATR's & any others                                                                                         | NO          |

Overall Rating :

|                                             |    |
|---------------------------------------------|----|
| Satisfactory (S)                            | —  |
| Satisfactory but requires Improvement (SRI) | RI |
| Unsatisfactory (U)                          | —  |

*Mh*  
09/1/2021  
(Signature)

NAME: Mihir Kumar

DESIGNATION: J-E