FIELD INSPECTION REPORT

Date of I	Inspection: 16/12/20 District : Bhagalpur		,
Division	; Bhagalpur Length (Km) : 0	440	
Name of	the Road: Darizapur Harnathpur 104d to Passan Tola	s mardal Told	
Scheme /	Programme: MMMSY (Sc)		
Package 1	No.: Road Id No.: 20-	703201356	•
Status of	the Project: Ongoing / Completed / Under Maintenance		an an an deil an
Work is a	case of: New Connectivity / Up gradation / Maintenance	æ	
SL. Nö.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	
f)	Contraction Joints provided or not (CC Pavement)	Yes / No	
g)	Cpmpaction of flank/slope & raincuts if any	Yes/No	4
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U	Spla
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	1
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	Gas -
4.	Compliance History		
a)	Status of ATR's & any others		
Overall R	Lating:		
	Satisfactory (S)	S	
	tisfactory but requires Improvement (SRI)		
	Unsatisfactory (U)		337
		- All	

Note:

NAME: NEERAJ KUHAR

DESIGNATION: 78

Signature