FIELD INSPECTION REPORT

Date of Inspection: 08-01-2021			District: Sarras & Pun	
Division: Patoxi			Length (km): 0.580 K.M	
Name of	the Road: M	akundpur in	nci chouk to pyareip	
	Programme:	MAINTENANCE		
Package No.:			Road Id No.;	
	the Project:	Ongoing/Complete	d/Under Maintenance	
Work is	a case of:	THOUSE THE CONTRACT OF THE PARTY OF THE PART	Up gradation/ Maintenance	
Sl. No.		Parameters to	be checked	Remarks
i.	Pavement			
a)	Road Junction condition			S/U
b)				
(c)	Riding Quality	S/U		
(d)	Road Camber	S/U		
e)	Whether free aggregates in	Yes/No		
1	Contraction Joints provided or not (CC Pavement)			Yes/No
		of flank/slope & rainc		Yes/No
2.				
	a) Condition of head walls in Hume pipe culverts in		pipe culverts including its painting	S/SRI/U
b)	241 4 4 2 3			S/SRI/U
(c)	2 11 /11/			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance			
a)	Status of ATR's & any others			

Overall Rating

Satisfactory (S)	1. 1. 1.
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	S. 15.

NAME: A CON KUMORA Styro DESIGNATION: Sirgh 08/01/2021 A.E (Signature)

Scanned with CamScanner