

# FIELD INSPECTION REPORT

|                                              |                                            |
|----------------------------------------------|--------------------------------------------|
| Date of Inspection : 10.01.2021              | District: Saron                            |
| Division : Chapra - 2                        | Length (km): 2.190 Km                      |
| Name of the Road: To 5 To Darwa Purab To 19. |                                            |
| Scheme/Programme: MAINTENANCE                | G.T.S.N.Y.                                 |
| Package No.:                                 | Road Id No.:                               |
| Status of the Project:                       | Ongoing/Completed/Under Maintenance        |
| Work is a case of:                           | New Connectivity/Up gradation/ Maintenance |

| Sl. No. | Parameters to be checked                                                                                             | Remarks    |
|---------|----------------------------------------------------------------------------------------------------------------------|------------|
| 1.      | <b>Pavement</b>                                                                                                      |            |
| a)      | Road Junction condition                                                                                              | ✓S/U       |
| b)      | Condition of Surfacing                                                                                               | -S/U       |
| c)      | Riding Quality                                                                                                       | ✓S/U       |
| d)      | Road Camber                                                                                                          | ✓S/U       |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No     |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No     |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No     |
| 2.      | <b>Cross Drainage</b>                                                                                                |            |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U No |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U No |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U No |
| 3.      | <b>Road Furniture</b>                                                                                                |            |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓Yes/No    |
| 4.      | <b>Compliance History</b>                                                                                            |            |
| a)      | Status of ATR's & any others                                                                                         |            |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S)                            |     |
| Satisfactory but requires Improvement (SRI) | SRI |
| Unsatisfactory (U)                          |     |

NAME:

DESIGNATION:

(Signature)

*[Signature]*  
10.01.2021  
JE  
(Isuapur)