

FIELD INSPECTION REPORT

Date of Inspection: 68.01-2021	District: Nalanda
Division: F&S	Length (km): 0.500 km
Name of the Road: - Hilsa Hasbanspur road to Chak Mohiddinpur	
Scheme/Programme: MAINTENANCE	MANGSY NDA (AE/12)
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	Under maintenance
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road/Junction condition	S/U - S
b)	Condition of Surfacing	S/U - S
c)	Riding Quality	S/U - S
d)	Road Camber	S/U - S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No - Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No - Yes
g)	Compaction of flank slope & raincuts if any	Yes/No - Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U - S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U / NO
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No - Yes
4.	Compliance History	
a)	Status of ATR's & any others	NO ATR

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 68-01-2021
 AE
 (Signature)

NAME: