## FIELD INSPECTION REPORT

|  |  |                                      | SIECTION REPORT  |  |  |
|--|--|--------------------------------------|--|--|--|
| Date o   | f Inspection:  | 5/1/2021                             | District:  | Man Pa   |  |
| Division:  |  |                                      | Length (km): 1.60 M.   |  |  |
| Schow  | of the Road,   | an her chor                          | old to cleaned hung  | via jardille   | bux  |
| Packag   | e/Programme  | MAINTENA                             | NCE  | 111  |  |
| Status   | of the Project:  |                                      | Road Id No.:   |  |  |
| Work i   | s a case of:   |                                      | pleted/Under Maintenance   |  |  |
| Sl. No.  | Salar Sections with Section Section 1  | BOOK OF THE STREET, BUT THE PARTY OF | ivity/Up gradation/ Mainte   | nance  | A A Property of the Park of th |
| A STATE OF THE PARTY OF THE PAR |  | Paramet                              | ers to be checked  | F  | lemarks  |
| 1.   | Pavement   |                                      |  |  |  |
| a)   | Road Junction condition  |                                      |  |  | S/U  |
| b)   | Condition of Surfacing   |                                      |  |  | S/U  |
| c)   | Riding Quality   |                                      |  | S/U  |  |
| d)   | Road Camber  |                                      |  |  | S/U  |
| e)   | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         |                                      |  |  | Yes/No   |
| f)   | Contraction Joints provided or not (CC Pavement)   |                                      |  | Yes/No   |  |
| g)   | Compaction of flank/slope & raincuts if any  |                                      |  | Yes/No   |  |
| 2.   | Cross Draina   | ge                                   |  | principle of the property of the principle of the princip |  |
| a)   | Condition of head walls in Hume pipe culverts including its painting   |                                      |  |  | S/SRI/U  |
| b)   | Condition of Abutment & Wing wails, Slab in RCC culverts S   |                                      |  | S/SRI/U  |  |
| c)   | Condition of railings/slab/approach for Bridges  |                                      |  | S/SRI/U  |  |
| 3.   | Road Furnitu   | senergy year                         | CONTROL OF THE PROPERTY OF THE |  |  |
| 1)   | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained |                                      |  |  | Yes/N  |
|  | Compliance H   | istory                               |  |  | A TO SERVICE STREET  |
| A 22 3 3 5 5 1   | Status of ATR'   |                                      | ***  |  | 1 No   |

Overall Rating

| Satisfactory (S)                            | S |
|---|---|
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          |   |

(Signature)

NAME: NAND KISHOR SHARMA

DESIGNATION: JUNSOR ENGINEER.