## FIELD INSPECTION REPORT

District: Cast dauferan Length (km): 0.705 09.01.21 Larnipur Bachanpus Date of Inspection : Division: Revered Name of the Road: PND Road to OTHESY (GEN) Road Id No.: 3190 8501233 MAINTENANCE Scheme/Programme: Quanting/Completed/Under Maintenance Package No.: New Connectivity/Up gradation/ Maintenance Status of the Project: Remarks Work is a case of: Parameters to be checked SI. No. Payement S/U 1. Road Junction condition S/U (E Condition of Surfacing S/U b) Riding Quality c) S/U Road Camber d) Whether free from defects such as visible crucks, exposed Yes/No aggregates in case of Co Pavement. c) Yes/No Contraction Joints provided or not (CC Pavement) D) Yes/No Compaction of flank/slope & raincuts if any g) Cross Drainage 2. Condition of head walls in Hume pipe culverts including its painting S/SRI/U ก) Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U b) S/SRI/U Condition of railings/slab/approach for Bridges c) Road Furniture 3. Whether sign boards/informatory/cautionary Board/km & 200m Ycs/No stones/Pavement road markings are provided and maintained a) Compliance History 4. Status of ATR's & any others

Overall Rating

a)

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Olitlish Kumer Lings DESIGNATION: Junior Engineer, Mauradens