

FIELD INSPECTION REPORT

Date of Inspection :	9/1/21	District:	East Champaran
Division :	Raxaul	Length (km):	0.988
Name of the Road:	L-50 Senuraya to Aher Tola		
Scheme/Programme:	MAINTENANCE	MYG5Y	
Package No.:		Road Id No.:	31708501251
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N.A.

Overall Rating :

Satisfactory (S)	51
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
9/1/21

(Signature)

NAME: *Milind Kumar Singh*

DESIGNATION: *Junior Engineer, Raxaul*