

Date of Inspection:	07/11/21	District:	NALANDA
Division:	HILSA	Length (km):	1.360 km
Name of the Road:	Ewangan-Bihar road to Saidadi Bigha (Ranchhandi Master house)		
Scheme/Programme:	MAINTENANCE ✓		
Package No.:	MHGSY	Road Id No.	
Status of the Project:	Ongoing/Completed/Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	YES/NO
f)	Contraction Joints provided or not (CC Pavement)	YES/NO
g)	Compaction of flank slope & raincuts if any	YES/NO
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	YES/NO Maintenance board not Also
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

INTANIL KUMAR
NAME:

(Signature) 07/11/21