

FIELD INSPECTION REPORT

Date of Inspection : 11.03.2021	District: Nalanda
Division: H&G	Length (km): 0.700 Km
Name of the Road: 4150 Patuha Ghosh PMGSY Road to Gwalgho	
Scheme/Programme: MAINTNANCE	
Package No.:	Road Id No.:
Status of the Project: ☒ Ongoing ☐ Completed ☐ Under Maintenance	
Work is a case of: ☒ New Connectivity ☐ Up gradation ☐ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ SR
b)	Condition of Surfacing	✓ SR
c)	Riding Quality	✓ SR
d)	Road Camber	✓ SR
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓ Yes/No
f)	Contractor joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SR
b)	Condition of Abutment & Wing walls Slab in RCC culverts	S/SR: N/A
c)	Condition of earthen/stone approach for Bridges	S/SR: N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m marker/pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO ATR

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

- S -

Rampril Choudhary

Rampril Choudhary
11.03.2021
(Signature) J.E.