

FIELD INSPECTION REPORT

Date of Inspection: 10/01/2021	District: Sonapatna
Division: ROSALA	Length (km): 0.403 km
Name of the Road: Link Road (Rosala Gas Station to Mahant) to Panchsagar to 1/6	
Scheme/Programme: MAINTENANCE	
Package No.: 24/S.D./2020-021	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/P
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/P
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/P
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/O

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:- Dindayal chowhan

DESIGNATION:- J E / RWD, Rosala

10/01/2021
(Signature) J. E. / RWD