

FIELD INSPECTION REPORT

Date of Inspection : 08-01-2021 District: Samastipur
 Division : Patoti Length (km): - 2.390 KM
 Name of the Road: Saraswati Chaur to mmgsy
 Scheme/Programme: MAINTENANCE mmgsy
 Package No.: Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance - ongoing
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U N/A
b)	Condition of Surfacing	S/U N/A
c)	Riding Quality	S/U N/A
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No N/A
4.	Compliance History	
a)	Status of ATR's & any others	No any ATR

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	/
Unsatisfactory (U)	/

Ravi
 (Signature) 08-01-2020

NAME: Ravi Ranjan
 DESIGNATION: J-E