

FIELD INSPECTION REPORT

PM 657-11

Date of Inspection: 7/1/21

Division: 2

District: Chaurasahi

Length (km): 1.5

Name of the Road: 2 - Kachhi Chaurasahi

Scheme Programme: MAINTENANCE

Package No: 22-3032-05

Road Id No: 1

Status of the Project: Category: Completed Under Maintenance

Work is a case of: New Connectivity / Upgradation / Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S
b)	Condition of Surfacing	✓ S
c)	Riding Quality	✓ S
d)	Road Camber	✓ S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ S
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	Yes/No
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	✓ No
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Signature: Gautam Das

(Signature)

NAME:

S.B.