FIELD INSPECTION REPORT

	Inspection: 0	9.01.2021	District: Subaul		
Division .			Paul		
	the Road:		Length (km): 1.590 km		
Scheme/	Programme:	MAINTENANCE	ushari Tolq.		
Package	No.:		Road Id No.: 21004.91		
Status o	f the Project:	Ongoing/Completed	Road Id No.: 2100491 /Under Maintenance	3018	
CONTRACTOR STATE OF THE PARTY O	a case of:	New Connectivity/L	Jp gradation/ Maintenance		
Sl. No.	A STATE OF THE PARTY OF THE PAR	Parameters to	he chacked	10.02/10.00000 miles	
1.	Pavement	A STATE OF THE STATE OF		Remarks	
a)	Road Junction condition				
b)	Condition of Surfacing			S/U	
c)				S/U	
d)	Riding Quality Road Camber			S/U	
				S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			~	
g)	Compaction o	Yes/No			
2.	Cross Draina	Yes/No			
Carp and says a		Committee of the commit			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U N	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U N	
3.	Road Furniture			di d	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance History				
a)	Status of ATR's & any others			V.	
	The second of th			No	

Overall Rating :

Satisfactory (S)	(5)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: SHASHI KUMAR

DESIGNATION: JE Normali