FIELD INSPECTION REPORT

ate	of Inspection:		ECTION REPO	
Division: RWD Dalsinghsarai			District: Samastipur	
Nan	ne of Road: To6		Length(km):	
	eme / Programme:	MAINTENANCE	esatori Tala	
	kage No:	I I I I I I I I I I I I I I I I I I I	Road Id No: MM	RCY
Stat	us of the Project: Or	ngoing/Completed/Unde	r Mainterance	4-5
Wo	rk is a case of:		gradation/ Maintenance	Marie Marie Andrews
Sl. No		Parameters to be		Remarks
1	Pavement		HOLESON DE LA CONTRACTOR DEL CONTRACTOR DE LA CONTRACTOR	
a)	Road Junction Condition			2
b)	Condition of Surfacing			<u>S</u>
c)	Riding Quality			2
d)	Road Camber			2
e)	Whether free from aggregates in case of	defects such as visible or of CC Pavement	racks, exposed	2
f)	Construction Joint provided or not(CC Pavement)			2
g)	Compaction of flank/slope & raincuts if any			SRI
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			2
b)	Condition of Abutment & Wing walls , Slab in RCC culverts			
c)	Condition of railings/slab/approach for Bridge			
3	Road Furniture			
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			SRI
4	Compliance Histor	y		STORES EN
a)	Status of ATR's & a	ny others		

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	SRI
Unsatisfactory(U)	

Aserta 11/01/21 (Signature)

NAME: Deepar chambra sinta DESIGNATION: J.E.