FIELD INSPECTION REPORT

Pa	te of Inspection:		SETTON KET OF	(1
Division: RWD Dalsinghsarai			District: Samastipur	
Name of Road : Length (Kin).				
	eme / Programme:		e Siman	
Pac	kage No:	MAINTENANCE		
			Road Id No: GISN	Y
Wo	rk is a case of:	going/Completed/Under	Maintenance	
SI.	in is a case of:	New Connectivity/ Up g	radation/ Maintenance	1
No		Parameters to be C	hecked	Remarks
1	Pavement			
a)	Road Junction Cond	ition		5
b)	Condition of Surfacing			2
c)	Riding Quality			2
d)	Road Camber			2
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			2
f)	Constraction Joint provided or not(CC Pavement)			2
g)	C .: CC 1/1 8 .: +: F			SRI
2	Cross Drainage			
a)	Condition of head wa including its painting	lls in Hume pipe culverts		2
5)	Condition of Abutmer	nt & Wing walls , Slab in	RCC culverts	
;)	Condition of railings/s	slab/approach for Bridge		-
	Road Furniture			A. C. Williams
)	Whether sign boards/i stones/Pavement road	nformation/cautionary Bo markings are provided an	pard/km & 200m ad maintained	2
-	Compliance History			
5	Status of ATR's & any	others		A THE PARTY OF THE
1				

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	SRI
Unsatisfactory(U)	

Alirla (Signature)

NAME: Deepar Clarofra sinta DESIGNATION: J.E.