

Block - Chaugai

FIELD INSPECTION REPORT

Date of Inspection : 06/01/2021

District: Buxar

Division: Dumraon

Length (km): 0.700 KM

Name of the Road:

Kharwali Pandeypur Path to Thori Pachiyani Pokhra

Scheme/Programme:

MAINTENANCE

GT-T.S.N-9

Package No.:

Road Id No.:

Status of the Project:

Ongoing ☒ Completed ☐ Under Maintenance ☐

Work is a case of:

New Connectivity ☐ Up gradation ☐ Maintenance ☒

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	ST
a)	Road Junction condition	ST
b)	Condition of Surfacing	ST
c)	Riding Quality	ST
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of Bank/slope & raincuts if any	Yes/No
2.	Gross Drainage	
a)	Condition of head walls in flume pipe culverts including its painting	S/SRI/L
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/L
c)	Condition of railings/slab/approach for Bridges	S/SRI/L
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 100m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATRs & any others	

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

work delayed aquined problem.

(Signature)

NAME:

DESIGNATION:

06/01/21
JEA2
6/01/21
ME