

FIELD INSPECTION REPORT

Date of Inspection : 06-01-21	District: Saharshi
Division : Beland	Length (km) 0.130
Name of the Road: Sangay Singh house to Narha to Phab Tola	
Scheme/Programme: MAINTENANCE	GrTSNY
Package No.:	Road Id No.
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	✓ S U
a)	Road Junction condition	✓ S U
b)	Condition of Surfacing	✓ S U
c)	Riding Quality	✓ S U
d)	Road Camber	✓ S U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	✓ S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	✓ Yes/No
a)	Whether sign boards/informatory/cautionary Board/Mark & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	No
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

[Signature]
b-1-21
(Signature)

NAME: Ginish Prasad Sah

DESIGNATION: J.E, RWD, Beland