

FIELD INSPECTION REPORT I

Date of Inspection : 06-1-21	District: Sifamashi
Division : Belsond.	Length (km): 0.30
Name of the Road: Durga Bailha house To Gharwara R.O. Road to Koltia.	
Scheme/Programme: MAINTENANCE	GTSNY
Package No.:	Road Id No.
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓
b)	Condition of Surfacing	✓
c)	Riding Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓/No
f)	Contraction Joints provided or not (CC Pavement)	✓/No
g)	Compaction of flank/slope & raincuts if any	✓/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓/SRT/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓/SRT/U
c)	Condition of railings/slab/approach for Bridges	✓/SRT/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/200m stones/Pavement road markings are provided and maintained	✓/Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S) ✓

Satisfactory but requires Improvement (SRI) X

Unsatisfactory (U) X

[Signature]
6.1.21
(Signature)

NAME: Ginish Prasad Sen

DESIGNATION: J. E, RWD, Belsond