


FIELD INSPECTION REPORT

Date of Inspection : 06-1-21		District: Sitamahi	
Division : Beland		Length (km): 0.98	
Name of the Road: Gueddu Singh home to Rakhela to Grahman			
Scheme/Programme:		MAINTENANCE GTSNY	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		✓ S/U
b)	Condition of Surfacing		✓ S/U
c)	Riding Quality		✓ S/U
d)	Road Camber		✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)		✓ Yes/No
g)	Compaction of flank/slope & raincuts if any		✓ Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		✓ Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		N/A

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	x
Unsatisfactory (U)	x


 6.1.21
 (Signature)

NAME: G. Prasad Sah

DESIGNATION: I.E. RWD Beland