

Block - Dinara.

FIELD INSPECTION REPORT

Date of Inspection:		District: <u>Rohas</u>	
Division: <u>R.W.D. Bilva gang</u>		Length (km): <u>2.75 km</u> 1.337 km.	
Name of the Road: <u>Baram Dinara Road to Khairaki</u>			
Scheme/Programme: <u>MAINTENANCE</u>		Road Id No.: <u>10301300203</u>	
Package No.:			
Status of the Project: <u>Ongoing/Completed Under Maintenance</u>			
Work is a case of: <u>New/Improvement/Up gradation/Amendment</u>			
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		✓ SU
b)	Condition of Surfacing		✓ SU
c)	Riding Quality		✓ SU
d)	Road Camber		✓ SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		✓ Yes/No
f)	Construction joints provided or not (CC Pavement)		✓ Yes/No
g)	Compaction of flank/diaphragm & camber if any		✓ Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		✓ S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SR/U NA
c)	Condition of railing/slab approach for Bridges		S/SR/U NA
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained		200m ✓ Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SR)	
Unsatisfactory (U)	

R. Patel
09/01/21
(Signature)

NAME: Rakash Patel