

Block-chaugai

FIELD INSPECTION REPORT

Date of Inspection : 06/01/2021

District: Buxar

Division : Dumraon

Length (km): 1.800 KM

Name of the Road: Koyan Sari Chaugai Path to Bali Ke Dera

Scheme/Programme: MAINTENANCE

G.T.S. N.Y.

Package No.:

Road Id No.:

Status of the Project: ☒ Ongoing ☐ Completed ☐ Under MaintenanceWork is a case of: ☒ New Connectivity ☐ Up gradation ☐ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	S/L
a)	Road Junction condition	S/L
b)	Condition of Surfacing	S/L
c)	Riding Quality	S/L
d)	Road Camber	S/L
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of Bank/slope & raincuts if any	Yes/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATRs & any others.	

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Work delay due to land acquired.

(Signature)

NAME:

DESIGNATION:

by
06/01/21
JEH3
06/01/21