## FIELD INSPECTION REPORT

Data of I						
Date of Inspection: 13/01/2021 District: Ro			Ro	HTAS		
Division: SASARAM-2			Length (km):	1.00	1.005	
Name of	the Road: Sty	ANAK KOK	T (SUGENAWISAH) BY	1CAL	MAHITZ 2	YADAY
THE RESERVE AND ADDRESS OF THE PARTY OF THE		MAINTENANC			The state of the s	
Package			Road Id No.:			
The Park Street of the Park Street or the Park Stre			ted/Under Maintenance		The second secon	
Work is	a case of:	New Connectivit	y/Up gradation/ Maintenance			
SI. No.		Parameters	to be checked		Remarks	
1.	Pavement				A 100 CO	
n)	Road Junction condition				SAU	
b)	Condition of Surfacing				SAU	
c)	Riding Quality				S/U	
d)	Road Camber				S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				YesNo	
f)	Contraction Joints provided or not (CC Pavement)				Yes/No	
g)	Compaction of flank/slope & raincuts if any				Yes/No	
2.	Cross Drainage				The second secon	
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U					
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				S/SRI/U	
c)	Condition of railings/slab/approach for Bridges				S/SRI/U	A Company of the Comp
3.	Road Furniture					
a)	Whether sign b stones/Pavement	oards/informato road markings a	ry/cautionary Board/km & re provided and maintained	200m	Yes/No	
4.	Compliance His	tory				
a)	Status of ATR's	& any others			-NO -	-
-	The state of the s					3 2

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Sylvalcas\_ (3|01|202| (Signature)

NAME: BIBHAKAR KUMBR