

FIELD INSPECTION REPORT

Date of Inspection : 25/12/20		District: 13.01.00 (m. 00)
Division: Bellary		Length (km): 1.160
Name of the Road: Balharthy Barmore to Chik. A. B.		
Scheme/Programme: MAINTENANCE		
Package No.: 41MGLF		Road Id No.: 3180 2800 1205
Status of the Project: Ongoing/Completed/Under Maintenance		On going
Work is a case of: New Connectivity/Up gradation/ Maintenance		road pavement

Sr. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & reinputs if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A
c)	Condition of railings/slab/approach for Bridges	N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)

NAME: JONIL KUNAR

DESIGNATION: JE