



Vijay

1/8/2021 at 6:41 PM



**FIELD INSPECTION REPORT** mmasy.

Date of Inspection : 20.12.20		District: West Champaran
Division : Naakachya gany		Length (km):
Name of the Road: Shamba Mahato ke gha se Kabinistan		
Scheme/Programme: MAINTENANCE		Road Id No.:
Package No.:		Status of the Project: Ongoing/Completed/Under Maintenance
Work is a case of: New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No
f)	Contraction Joints provided or not (CC Pavement)	S
g)	Compaction of flank/slope & raincuts if any	S
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA
c)	Condition of railings/slab/approach for Bridges	NA
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	S

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

20-12-20  
 (Signature)

NAME: VIJAY PRATAP SINGH

DESIGNATION: JE

