

FIELD INSPECTION REPORT

Date of Inspection : 12.01.2021		District: H. Champaran
Division : Belthari		Length (km): 3.0 km
Name of the Road: Ganauli khat to Ganauli Husharoli		
Scheme/Programme: MAINTENANCE		
Package No.: BR-37R-617		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		UNDBR Maint
Work is a case of: New Connectivity/Up gradation/ Maintenance		Maint.
Sl. No.	Parameters to be checked	Remarks
1.	Payement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	yes
f)	Contraction Joints provided or not (CC Pavement)	yes
g)	Compaction of flank/slope & raincuts if any	yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A
c)	Condition of railings/slab/approach for Bridges	N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	yes
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


12-01-2021
(Signature)

NAME: J. UNIL KUNAR

DESIGNATION: J.C