

Block - Chaugai

FIELD INSPECTION REPORT

Date of Inspection: 06/01/2021

District: Buxar

Division: Dumraon

Length (km): 0.220M

Name of the Road: Chaugai Bhadi road to Bhulwan dera Bhaya Braw Patti.

Scheme/Programme: MAINTENANCE

mmGSY (gen)

Package No.:

Road Id No.:

Status of the Project: Ongoing ☒ Completed ☐ Under Maintenance

Work is a case of: New Connectivity ☐ Up gradation ☐ Maintenance ☒

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	SU
a)	Road Junction condition	SU
b)	Condition of Surfacing	SU
c)	Riding Quality	SU
d)	Road Camber	SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of Bank/slope & raincuts if any	Yes/No
2.	Gross Drainage	S/SRI/U
a)	Condition of head walls in/lume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Land problem

(Signature)

NAME:

DESIGNATION:

06/01/21
JE

6/01/21
BE