

FIELD INSPECTION REPORT

Mangla

145
241

Date of Inspection:	03/01/21	District:	Saran
Division:	Chhapara-2	Length (km):	5.17 Km
Name of the Road:	Boreja to Tappur		
Scheme/Programme:	MAINTENANCE		M. C. S. A. R.
Package No.:		Road Id No.:	3130630.2010
Status of the Project:	Ongoing Completed Under Maintenance		work not started
Work is a case of:	New Connectivity Up gradation Maintenance		

SL No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

work not started

Unsatisfactory.

Con 31/1/21
(Signature)

NAME: Chandraver Narayan
DESIGNATION: T. A. (Ex- Er)