

# FIELD INSPECTION REPORT

Manglu

149  
289

Date of Inspection : 03/01/21 District: Saran

Division : Chapara - 2 Length (km): 2.110 Km

Name of the Road: Kachipar to Bagaiyan

Scheme/Programme: MAINTENANCE M. G. S. A. R.

Package No.: Road Id No.: 31306302042

Status of the Project: Ongoing Completed/Under Maintenance **Work Not started**

Work is a case of: New Connectivity Up gradation Maintenance

| SL No. | Parameters to be checked                                                                                             | Remarks |
|--------|----------------------------------------------------------------------------------------------------------------------|---------|
| 1      | Pavement                                                                                                             |         |
| a)     | Road Junction condition                                                                                              | S/U     |
| b)     | Condition of Surfacing                                                                                               | S/U     |
| c)     | Riding Quality                                                                                                       | S/U     |
| d)     | Road Camber                                                                                                          | S/U     |
| e)     | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No  |
| f)     | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No  |
| g)     | Compaction of flank/slope & raincuts if any                                                                          | Yes/No  |
| 2      | Cross Drainage                                                                                                       |         |
| a)     | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U |
| b)     | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U |
| c)     | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U |
| 3      | Road Furniture                                                                                                       |         |
| a)     | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No  |
| 4      | Compliance History                                                                                                   |         |
| a)     | Status of ATR's & any others                                                                                         |         |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            |   |
| Satisfactory but requires Improvement (SRI) | 1 |
| Unsatisfactory (U)                          | 0 |

Work Not started

Unsatisfactory

On 03/01/21  
(Signature)

NAME: Chandravir Narayan  
DESIGNATION: T. A. (Ex. En)