

## Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Bihakur

2 Name of Block/Road :- Najeerpur Chowk to Makarandpur Gao tak. (naighat)

(A) For Road: ☒

1. Damage Location/Chainage :- 0.025 km, 0.100 km, 0.200 km,
2. Damage Length :- 53.3 m (0.0533 km)
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:- brick bats.
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :- 0.0533 km

(B) For Bridge: ☒

1. Damage Location/Chainage :-
2. Damage Length :- 0.053 km
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:- brick bats.
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :- 0.053 km

Signature of JE/AE/EE

  
16.12.20  
Signature

(Name of Inspection)

EE

RWD work Division  
Najeerpur East-1

## GENERAL ABSTRACT

Name of Road      Najeerpur Chowk to Makrandpur Gao Tak

District              Muzaffarpur

Block                Gaighat


Division            Muzaffarpur East-2


Length of Road (in Km)


2.000 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	7.154
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	7.154
TOTAL COST OF PROJECT IN LACS =		7.154


Saw 7.15 lac

  
JE  
RWD

  
AE  
RWD

  
EE  
RWD

Technically Approved for Rs 7.15 lac  
(Rupees seven lac. fifteen thousand only.)

  
SE  
RWD work circle  
muzaffarpur.