

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- 6797 ~~Prabakar~~

2 Name of Block/Road :- S Noor to S Noor (Gaighat)


(A) For Road: ✓

1. Damage Location/Chainage :- 0.300km, 0.550km, 0.850km, 1.20km, 1.50km, 1.650km
2. Damage Length :- 544.5 M (0.5445 km) (Length: 1.78km)
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Brck bats
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.544 km (0.5445 km)

X (B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


24.12.20

Signature

(Name of Inspection)

EE

RWD work Division

muzzafarpur Cantt

GENERAL ABSTRACT

Name of Road S Noor to S Noor

District Muzaffarpur

Block Gaighat


Division Muzaffarpur East-2

Length of Road (in Km) 1.780 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	9.552
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	9.552
TOTAL COST OF PROJECT IN LACS =		9.552


SAY 9.55 LAC.


JE
RWD


AE
RWD


RWD

Technically Approved for Rs 9.55 Lac.
(Rupees nine lac, fifty five thousand only.)


SE 4-1-21
PWD work circle
muzaffarpur