

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Prakash

2 Name of Block/Road :- Jangam High school to Bhura Chowk (Gaighat)

(A) For Road: ✓

1. Damage Location/Chainage :- 0.30km, 0.60km, 1.50km, 2.4km, 3.5km, 5.50km, 6.90km
2. Damage Length :- 288.84 m (0.28884 km)
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- brick bats.
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.288 km (0.28884 km)

(B) For Bridge: ✗

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

EE

RWD work Division

myzafar pur East-1

GENERAL ABSTRACT

Name of Road Jarang High School to Bhusara Chowk Tak

District Muzaffarpur

Block Gaighat

Division Muzaffarpur East-2

Length of Road (in Km)

7.600 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	4.250
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	4.250
TOTAL COST OF PROJECT IN LACS =		4.250

Say. 4.25 Lac.

[Signature]
29/12/20

[Signature]
21/12/20

JE
RWD

[Signature]
7/12/20

AE
RWD

[Signature]
29/12/20

EE
RWD

Technically Approved for Rs. 4.25 Lac.
(Rupees four Lac, twenty five thousand only.)

[Signature]
SE 4.1.21
PWD work circle
muzaffarpur