

## Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- NH 57 to Sakni tola (gkaighat)

(A) For Road: ✓

1. Damage Location/Chainage :- 0.00 to 20.020 km

(Length 0.780 km)

2. Damage Length :- 20.1 m

3. Nature of Damage :-

4. Details of Restoration Works :-

(i) Material being used in Restoration works:- Brick bats

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length :- 0.020 km

✗ (B) For Bridge:

1. Damage Location/Chainage :-

2. Damage Length :-

3. Nature of Damage :-

4. Details of Restoration Works :-

(i) Material being used in Restoration works:-

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length :-

Signature of JE/AE/EE

Signature

(Name of Inspection)

EE

RWD work Division

Muzaffarpur East-1

### GENERAL ABSTRACT

Name of Road NH-57 to Sahni Tola Gaighat

District Muzaffarpur

Block Gaighat

Division Muzaffarpur East-2

Length of Road (in Km) 0.780 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	0.381
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	0.381
TOTAL COST OF PROJECT IN LACS =		0.381

Says. 0.38 lac.

*[Signature]*  
4/12/20  
JE  
RWD

*[Signature]*  
12/12/20  
AE  
RWD

*[Signature]*  
09/12  
EE  
RWD

Technically Approved for Rs 0.38 lac  
(Rupees thirty eight thousand only.)

*[Signature]*  
22-12-20  
SE  
RWD work circle  
muzaffarpur.