

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- Repair of road from Gussardhikpur to Pannagar Bhusra
main road. (Ghaighat)

(A) For Road: ✓

1. Damage Location/Chainage :- 1.20km, 1.6 km, 2.5km, 2.8km, 3.20km, 3.8km
2. Damage Length :- 730-55m (0.73055km) (Length = 4.20km)
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Brick bats
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:
 - (iv) Restored Length :- 0.730 km (0.73055 km)

✗ (B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


16/12/20

Signature

(Name of Inspection)

EE

RWD work Division

Muzaffarpur Ecvt-1


GENERAL ABSTRACT


Name of Road Repair of Road from Gussadhinpur to Ram Nagar Bhusra Main Road
District Muzaffarpur
Block Gaihat
Division Muzaffarpur East-2
Length of Road (in Km) 4.200 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	14.512
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	14.512
TOTAL COST OF PROJECT IN LACS =		14.512


Says 14.51 lac


7/12/20
JE
RWD


7/12/20
AE
RWD


EE
RWD

Technically approved for Rs 14.51 lac
(Rupees fourteen lac, fifty one thousand only).


7/12/20
SE
RWD work circle
muzaffarpur.